



## Custom Track Service Percent Worn

**HOLT TEXAS LTD.**

**HOWARDMCANEAR EQUIPMENT**  
(0585540)

Prepared By: Matthew Davis

<b>Model</b>	D8T	<b>Job Site</b>	Howard-McAnear Temple		<b>Inspection Date</b>	02Sep21
<b>Manufacturer</b>	Caterpillar		<u>Left</u>	<u>Right</u>	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	FMC00558	<b>Track Sag (56 mm - 76 mm)</b>	--	--	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	--	<b>Frame Ext (max 152 mm)</b>	85 mm	80 mm	<b><u>Underfoot Conditions</u></b>	
<b>Hour Meter Reading</b>	5,742	<b>Frame Ext %</b>	56%	53%	<b>Impact</b>	Moderate
<b>Hours Per Week</b>	--	<b>Dry Joints</b>	--	--	<b>Abrasion</b>	Moderate
<b><u>Total Odometer Reading</u></b>	--				<b>Moisture</b>	Moderate
<b>Forward Odometer</b>	--				<b>Packing</b>	Moderate
<b>Reverse Odometer</b>	--				<b>Bushing Allowable Wear</b>	Greater
					<b>Link Allowable Wear</b>	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (mm)		Percent Worn	
Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
<b>Link Assemblies</b>	<b>Left:2726009</b>				<b>Right:2726009</b>				<b>Pitch:8.5 in (215.9 mm)</b>		<b>Sections:44</b>			
<b>Track Link</b>	8E4513	8E4513	Original	Original	--	--	--	--	--	--	47 (U)	47.1 (U)	6%	6%
<b>Bushing (Ext)</b>	6Y3914	6Y3914	Original	Original	--	--	--	--	--	--	14 (U)	14 (U)	20%	20%
<b>Track Shoe</b>	<b>Left Width:--</b>				<b>Right Width:--</b>									
	7T2392	7T2392	Original	Original	--	--	--	--	--	--	62 (D)	62 (D)	42%	42%
<b>Idlers</b>														
<b>Front</b>	2440878	2440878	Original	Original	--	--	--	--	--	--	23 (D)	23 (D)	26%	26%
<b>Rear</b>	2440878	2440878	Original	Original	--	--	--	--	--	--	23.5 (D)	23.5 (D)	30%	30%
<b>Carrier Roller</b>														
<b>Front</b>	2460775	2460775	Original	Original	--	--	--	--	--	--	243 (C)	241 (C)	8%	12%
<b>Track Roller</b>														
<b>Front</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	58.2 (U)	58.3 (U)	19%	18%
<b>2</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	58.1 (U)	58.2 (U)	19%	19%
<b>3</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	57.9 (U)	56.7 (U)	11%	17%
<b>4</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	56.9 (U)	57.8 (U)	16%	11%
<b>5</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	57.8 (U)	57.8 (U)	11%	11%
<b>6</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	57.6 (U)	57.8 (U)	12%	11%
<b>7</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	57.8 (U)	58.9 (U)	20%	16%
<b>8</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	58.9 (U)	58.6 (U)	16%	17%
<b>Sprocket</b>														

	3145462	3145462	Original	Original	--	--	--	--	--	--	237 (T)	237 (T)	10%	10%
CONDITION: Good											CONDITION: Good			

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape

## General Recommendations

--