



## Custom Track Service Percent Worn

**HOLT TEXAS LTD.**

**HOWARDMCANEAR EQUIPMENT**  
(0585540)

Prepared By: Christopher Thornton

<b>Model</b>	326FL	<b>Job Site</b>	HM Yard	<b>Inspection Date</b>	10-Nov-2020
<b>Manufacturer</b>	Caterpillar		Temple	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	WGL00274		<u>Left</u> <u>Right</u>	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	WGL274	<b>Track Sag</b>	-- --	<b><u>Underfoot Conditions</u></b>	
<b>Hour Meter Reading</b>	3,949.1	<b>Frame Ext</b>	-- --	<b>Impact</b>	Moderate
<b>Hours Per Week</b>	--	<b>Dry Joints</b>	-- --	<b>Abrasion</b>	Moderate
<b><u>Total Odometer Reading</u></b>	--	<b>Internal Wear</b>	0% 0%	<b>Moisture</b>	Moderate
<b>Forward Odometer</b>	--		29.95 29.95	<b>Packing</b>	Moderate
<b>Reverse Odometer</b>	--		in in	<b>Bushing Allowable Wear</b>	Greater
				<b>Link Allowable Wear</b>	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
<b>Track Link</b>		<b>Left Link Assembly:3379044</b>				<b>Right Link Assembly:3379044</b>									
	3359246	3359246	Original	Original	09Nov20	09Nov20	--	--	--	--	1.16 (U)	1.15 (U)	23%	28%	
<b>Track Bushing</b>															
	1903523	1903523	Original	Original	09Nov20	09Nov20	--	--	--	--	0.43 (U)	0.43 (U)	13%	13%	
<b>Track Shoe</b>		<b>Left Width:31.1in</b>				<b>Right Width:31.1in</b>									
	5278992	5278992	Original	Original	09Nov20	09Nov20	--	--	--	--	1.53 (U)	1.53 (U)	8%	8%	
<b>Idlers</b>															
<b>Front</b>	1156337	1156337	Original	Original	09Nov20	09Nov20	--	--	--	--	0.78 (D)	0.79 (D)	21%	27%	
<b>Carrier Roller</b>															
<b>Front</b>	8E5600	8E5600	Original	Original	09Nov20	09Nov20	--	--	--	--	4.64 (C)	4.64 (C)	12%	12%	
<b>2</b>	8E5600	8E5600	Original	Original	09Nov20	09Nov20	--	--	--	--	4.64 (C)	4.64 (C)	12%	12%	
<b>Track Roller</b>															
<b>Front</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	1.71 (U)	1.7 (U)	8%	12%	
<b>2</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	1.72 (U)	1.73 (U)	4%	0%	
<b>3</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	--	--	--	--	
CONDITION: Guarded							CONDITION: Guarded								
<b>4</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	1.73 (U)	1.73 (U)	0%	0%	
<b>5</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	1.73 (U)	1.73 (U)	0%	0%	
<b>6</b>	S 4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	--	--	--	--	
CONDITION: Guarded							CONDITION: Guarded								
											1.73	1.72			

7	S	4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	(U)	(U)	0%	4%
8	S	4289769	4289769	Original	Original	09Nov20	09Nov20	--	--	--	--	1.72 (U)	1.72 (U)	4%	4%
<b>Sprocket</b>															
		1028134	1028134	Original	Original	09Nov20	09Nov20	--	--	--	--	--	--	--	--
CONDITION: Worn									CONDITION: Worn						

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

## General Recommendations

--