



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Christopher Thornton

Model 326FL	Job Site McAnear Temple Yard	Inspection Date 10-Nov-2020
Manufacturer Caterpillar	Left Right	Next Inspection Date 31-Dec-2099
Serial Number WGL00518	Track Sag -- --	Next Inspection Hours 4,404
Reference Number 518	Frame Ext -- --	Underfoot Conditions
Hour Meter Reading 3,991.1	Dry Joints -- --	Impact Moderate
Hours Per Week 0.19	Internal Wear 0% 0%	Abrasion Moderate
Total Odometer Reading --	29.95 i 29.95 i	Moisture Moderate
Forward Odometer --	n n	Packing Moderate
Reverse Odometer --		Bushing Allowable Wear Greater
		Link Allowable Wear Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
Track Link	Left Link Assembly:4991480				Right Link Assembly:4991480										
	3359246	3359246	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.13 (U)	1.14 (U)	37%	32%	
Track Bushing															
	1903523	1903523	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	0.38 (U)	0.38 (U)	45%	45%	
Track Shoe	Left Width:31in						Right Width:31in								
	5278992	5278992	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.47 (U)	1.47 (U)	16%	16%	
Idlers															
Front	1156337	1156337	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	0.82 (D)	0.82 (D)	46%	46%	
Carrier Roller															
Front	8E5600	8E5600	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	4.5 (C)	4.6 (C)	33%	18%	
2	8E5600	8E5600	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	4.5 (C)	4.5 (C)	33%	33%	
Track Roller															
Front	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.65 (U)	1.65 (U)	28%	28%
2	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.68 (U)	1.67 (U)	17%	21%
3	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	--	--	--	--
CONDITION: Guarded							CONDITION: Guarded								
4	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.68 (U)	1.67 (U)	17%	21%
5	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.67 (U)	1.69 (U)	21%	14%
CONDITION: Guarded							CONDITION: --								
6	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	--	--	--	--
CONDITION: Guarded							CONDITION: Guarded								
7	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.67 (U)	1.67 (U)	21%	21%

8	S	5089458	5089458	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	1.62 (U)	1.63 (U)	38%	35%
Sprocket															
		1028134	1028134	Original	Original	06Apr20	06Apr20	3432.7	3432.7	558.40	558.40	--	--	--	--
CONDITION: Worn									CONDITION: Worn						

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape

General Recommendations

--