



Custom Track Service Summary

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Adam Jetter

Model	320FL	Job Site	Howard Mcanear yard		Inspection Date	10-Nov-2020
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	YBM10063	Track Sag	0.3 in	0.2 in	Next Inspection Hours	--
Reference Number	--	Frame Ext	--	--	<u>Underfoot Conditions</u>	
Hour Meter Reading	2,930	Dry Joints	--	--	Impact	Moderate
Hours Per Week	--	Internal Wear	10%	10%	Abrasion	Moderate
<u>Total Odometer Reading</u>	--		30 in	30 in	Moisture	Moderate
Forward Odometer	--	Track Shoe Width	--	--	Packing	Moderate
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%				PROJECTED SMU AT 120%				PROJECTED DATE AT 100%	PROJECTED DATE AT 120%	
TRACK LINK	Good	5% (1.2 in)	5% (1.2 in)	--	--	--	--	--	--	--	--	--	--	
TRACK BUSHING	Good	20% (0.42 in)	20% (0.42 in)	--	--	--	--	--	--	--	--	--	--	
	NOTES: several dry seized links						NOTES:							
TRACK SHOE	Good	28% (1.37 in)	30% (1.35 in)	--	--	--	--	--	--	--	--	--	--	
FRONT IDLER	Good	1% (0.75 in)	1% (0.75 in)	--	--	--	--	--	--	--	--	--	--	
CARRIER ROLLER	Good	3% (4.7 in)	3% (4.7 in)	--	--	--	--	--	--	--	--	--	--	
FRONT														
2	Good	3% (4.7 in)	3% (4.7 in)	--	--	--	--	--	--	--	--	--	--	
TRACK ROLLER	Good	18% (1.64 in)	7% (1.67 in)	--	--	--	--	--	--	--	--	--	--	
FRONT														
2	Good	7% (1.67 in)	11% (1.66 in)	--	--	--	--	--	--	--	--	--	--	
3		--	--	--	--	--	--	--	--	--	--	--	--	
	CONDITION:Guarded						CONDITION:							
4	Good	11% (1.66 in)	4% (1.68 in)	--	--	--	--	--	--	--	--	--	--	
5	Good	14% (1.65 in)	7% (1.67 in)	--	--	--	--	--	--	--	--	--	--	
6		--	--	--	--	--	--	--	--	--	--	--	--	
	CONDITION:Guarded						CONDITION:Guarded							
7	Good	7% (1.67 in)	7% (1.67 in)	--	--	--	--	--	--	--	--	--	--	
8	Good	11% (1.66 in)	11% (1.66 in)	--	--	--	--	--	--	--	--	--	--	
SPROCKET	Good	--	--	--	--	--	--	--	--	--	--	--	--	
	CONDITION:Good						CONDITION:Good							

General Recommendations

--

Photos

Measurements

Track Bushings



Left Track Bushing 1
