



## Custom Track Service Percent Worn

**HOLT TEXAS LTD.**

**HOWARDMCANEAR EQUIPMENT**  
(0585540)

Prepared By: Matthew Davis

<b>Model</b>	D6TLGPVP	<b>Job Site</b>	Howard McAnear FW		<b>Inspection Date</b>	20-Apr-2021
<b>Manufacturer</b>	Caterpillar		<u>Left</u>	<u>Right</u>	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	KSB01364	<b>Track Sag (46 mm - 66 mm)</b>	--	--	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	1364	<b>Frame Ext (max 142 mm)</b>	83 mm	82 mm	<b><u>Underfoot Conditions</u></b>	
<b>Hour Meter Reading</b>	5,495	<b>Dry Joints</b>	--	--	<b>Impact</b>	--
<b>Hours Per Week</b>	--				<b>Abrasion</b>	--
<b><u>Total Odometer Reading</u></b>	--				<b>Moisture</b>	--
<b>Forward Odometer</b>	--				<b>Packing</b>	--
<b>Reverse Odometer</b>	--				<b>Bushing Allowable Wear</b>	Greater
					<b>Link Allowable Wear</b>	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (mm)		Percent Worn	
Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
<b>Link Assemblies</b>	<b>Left:3913925</b>				<b>Right:3913925</b>				<b>Pitch:8 in (203.2 mm)</b>		<b>Sections:45</b>			
<b>Track Link</b>	4182091	4182091	Original	Original	23Feb21	23Feb21	--	--	--	--	127 (D)	126 (D)	47%	57%
<b>Bushing (Ext)</b>	3966615	3966615	Original	Original	23Feb21	23Feb21	--	--	--	--	11 (U)	11.1 (U)	50%	45%
<b>Track Shoe</b>	<b>Left Width:790mm</b>						<b>Right Width:790mm</b>							
	2944980	2940569	Original	Original	--	23Feb21	--	--	--	--	50 (D)	50 (D)	58%	58%
<b>Idlers</b>														
<b>Front</b>	3954325	3954325	Original	Original	--	--	--	--	--	--	31 (D)	32 (D)	52%	56%
<b>Rear</b>	3954325	3954325	Original	Original	--	--	--	--	--	--	29 (D)	30 (D)	40%	48%
<b>Carrier Roller</b>														
<b>Front</b>	2355974	2355974	Original	Original	--	--	--	--	--	--	180 (C)	181 (C)	58%	56%
<b>Track Roller</b>														
<b>Front</b>	S	2880934	2880934	Original	Original	--	--	--	--	--	35.6 (U)	35.2 (U)	68%	69%
<b>2</b>	D	2880935	2880935	Original	Original	--	--	--	--	--	38 (U)	37.5 (U)	57%	60%
<b>3</b>	S	2880934	2880934	Original	Original	--	--	--	--	--	--	--	--	--
CONDITION: Guarded							CONDITION: --							
<b>4</b>	D	2880935	2880935	Original	Original	--	--	--	--	--	36.7 (U)	37 (U)	64%	62%
<b>5</b>	D	2880935	2880935	Original	Original	--	--	--	--	--	37.1 (U)	36.8 (U)	62%	63%
<b>6</b>	S	2880934	2880934	Original	Original	--	--	--	--	--	--	--	--	--
CONDITION: Guarded							CONDITION: --							
<b>7</b>	D	2880935	2880935	Original	Original	--	--	--	--	--	37.1 (U)	36.8 (U)	62%	63%
<b>8</b>	S	2880934	2880934	Original	Original	--	--	--	--	--	35.2 (U)	35.1 (U)	69%	70%
<b>Sprocket</b>														

3980972	3980972	Original	Original	--	--	--	--	--	--	219 (T)	219 (T)	32%	32%
---------	---------	----------	----------	----	----	----	----	----	----	---------	---------	-----	-----

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

## General Recommendations

--