



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Christopher Thornton

Model 326FL	Job Site HM Yard (Longview)	Inspection Date 21-Aug-2020
Manufacturer Caterpillar	Left Right	Next Inspection Date 10-Sep-2021
Serial Number WGL00438	Track Sag -- --	Next Inspection Hours 3,750
Reference Number 438	Frame Ext -- --	Underfoot Conditions
Hour Meter Reading 3,438.5	Dry Joints -- --	Impact Moderate
Hours Per Week 15.02	Internal Wear 0% 0%	Abrasion Moderate
Total Odometer Reading --	29.95 i 29.95 i	Moisture Moderate
Forward Odometer --	n n	Packing Moderate
Reverse Odometer --		Bushing Allowable Wear Greater
		Link Allowable Wear Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
Track Link	Left Link Assembly:3379044				Right Link Assembly:3379044										
	3359246	3359246	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.14 (U)	1.15 (U)	32%	28%	
Track Bushing															
	1903523	1903523	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	0.4 (U)	0.4 (U)	32%	32%	
Track Shoe	Left Width:31.1in						Right Width:31.1in								
	5278992	5278992	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.5 (U)	1.49 (U)	12%	13%	
Idlers															
Front	1156337	1156337	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	0.8 (D)	0.82 (D)	36%	48%	
Carrier Roller															
Front	8E5600	8E5600	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	4.5 (C)	4.5 (C)	33%	33%	
2	8E5600	8E5600	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	4.54 (C)	4.54 (C)	27%	27%	
Track Roller															
Front	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.67 (U)	1.67 (U)	24%	24%
2	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.69 (U)	1.7 (U)	16%	12%
3	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
4	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.7 (U)	1.7 (U)	12%	12%
5	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.7 (U)	1.7 (U)	12%	12%
6	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
7	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.7 (U)	1.69 (U)	12%	16%
8	S	4289769	4289769	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	1.67 (U)	1.65 (U)	24%	32%

Sprocket														
	1028134	1028134	Original	Original	20Aug20	20Aug20	2970.7	2970.7	467.80	467.80	--	--	--	--
CONDITION: Worn								CONDITION: Worn						

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape

General Recommendations

--