



Custom Track Service Summary

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Adam Jetter

Model	336EL	Job Site	Howard mcaneary yard		Inspection Date	10-Nov-2020
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	YCE00397	Track Sag	0.43 in	0.79 in	Next Inspection Hours	--
Reference Number	--	Frame Ext	--	--	<u>Underfoot Conditions</u>	
Hour Meter Reading	--	Dry Joints	0	0	Impact	Moderate
Hours Per Week	--	Internal Wear	24%	2%	Abrasion	Moderate
<u>Total Odometer Reading</u>	--		34.17 in	34.06 in	Moisture	Moderate
Forward Odometer	--	Track Shoe Width	33.46 in	33.46 in	Packing	Moderate
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% WORN		PROJECTED SMU AT 100%				PROJECTED SMU AT 120%				PROJECTED DATE AT 100%	PROJECTED DATE AT 120%
TRACK LINK	Good	10%	17%	--	--	--	--	--	--	--	--	--	--
		(1.33 in)	(1.31 in)										
TRACK BUSHING	Good	15%	22%	--	--	--	--	--	--	--	--	--	--
		(0.39 in)	(0.38 in)										
TRACK SHOE	Good	3%	0%	--	--	--	--	--	--	--	--	--	--
		(1.63 in)	(1.65 in)										
FRONT IDLER	Good	0%	0%	--	--	--	--	--	--	--	--	--	--
		(0.79 in)	(0.79 in)										
CARRIER ROLLER	Good	4%	4%	--	--	--	--	--	--	--	--	--	--
FRONT		(6.26 in)	(6.26 in)										
2	Good	4%	4%	--	--	--	--	--	--	--	--	--	--
		(6.26 in)	(6.26 in)										
TRACK ROLLER	Good	33%	20%	--	--	--	--	--	--	--	--	--	--
FRONT		(1.82 in)	(1.86 in)										
2	Good	10%	7%	--	--	--	--	--	--	--	--	--	--
		(1.89 in)	(1.9 in)										
3		--	--	--	--	--	--	--	--	--	--	--	--
		--	--										
		CONDITION:Guarded		CONDITION:									
4	Good	13%	10%	--	--	--	--	--	--	--	--	--	--
		(1.88 in)	(1.89 in)										
5		--	--	--	--	--	--	--	--	--	--	--	--
		--	--										
		CONDITION:Guarded		CONDITION:Guarded									
6	Good	10%	13%	--	--	--	--	--	--	--	--	--	--
		(1.89 in)	(1.88 in)										
7		--	--	--	--	--	--	--	--	--	--	--	--
		--	--										
		CONDITION:Guarded		CONDITION:Guarded									
8	Good	17%	13%	--	--	--	--	--	--	--	--	--	--
		(1.87 in)	(1.88 in)										
9	Good	27%	23%	--	--	--	--	--	--	--	--	--	--
		(1.84 in)	(1.85 in)										
SPROCKET	Good	--	--	--	--	--	--	--	--	--	--	--	--
		--	--										

General Recommendations

--