



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Christopher Thornton

Model	320FL	Job Site	Howard McAnear Longview Yard		Inspection Date	19-Nov-2020
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	NHD10147	Track Sag (1.6 in - 2.1 in)	--	--	Next Inspection Hours	--
Reference Number	Nhd10147	Frame Ext	--	--	<u>Underfoot Conditions</u>	
Hour Meter Reading	1,739.9	Dry Joints	--	--	Impact	Moderate
Hours Per Week	--	Internal Wear	0%	0%	Abrasion	Moderate
<u>Total Odometer Reading</u>	--		29.95 in	29.95 in	Moisture	Moderate
Forward Odometer	--				Packing	Moderate
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
Track Link		Left Link Assembly:1941133						Right Link Assembly:1941133							
	9W3137	9W3137	Original	Original	26Apr20	26Apr20	--	--	--	--	1.2 (U)	1.21 (U)	5%	0%	
Track Bushing															
	1903523	1903523	Original	Original	26Apr20	26Apr20	--	--	--	--	0.44 (U)	0.44 (U)	7%	7%	
Track Shoe		Left Width:27.6in						Right Width:27.6in							
	1265063	1265063	Original	Original	26Apr20	26Apr20	--	--	--	--	1.36 (U)	1.36 (U)	0%	0%	
Idlers															
Front	1156337	1156337	Original	Original	26Apr20	26Apr20	--	--	--	--	0.8 (D)	0.8 (D)	33%	33%	
Carrier Roller															
Front	8E5600	8E5600	Original	Original	26Apr20	26Apr20	--	--	--	--	4.65 (C)	4.65 (C)	10%	10%	
2	8E5600	8E5600	Original	Original	26Apr20	26Apr20	--	--	--	--	4.64 (C)	4.64 (C)	12%	12%	
Track Roller															
Front	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.64 (U)	1.65 (U)	18%	14%
2	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.67 (U)	1.66 (U)	7%	11%
3	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
4	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.67 (U)	1.68 (U)	7%	4%
5	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.66 (U)	1.68 (U)	11%	4%
6	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
7	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.67 (U)	1.68 (U)	7%	4%

8	S	1634143	1634143	Original	Original	26Apr20	26Apr20	--	--	--	--	1.67 (U)	1.65 (U)	7%	14%
Sprocket															
		8E9805	8E9805	Original	Original	26Apr20	26Apr20	--	--	--	--	--	--	--	--
CONDITION: Good									CONDITION: Good						

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

General Recommendations

--