

Custom Track Service **Summary**

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT (0585540)

Prepared By: Adam Jetter

Model	326FL	Job Site	Hov	Howard Mcanear yard		Inspection Date	10-Nov-2020
Manufacturer	Caterpillar			<u>Left</u>	<u>Right</u>	Next Inspection Date	
Serial Number	WGL00613	Track Sag		0.98 in	0.39 in	Next Inspection Hours	
Reference Number		Frame Ext				Underfoot Conditions	
Hour Meter Reading	2,173	Dry Joints		0	0	Impact	Moderate
Hours Per Week		Internal Wear		2%	2%	Abrasion	Moderate
Total Odometer Reading	<u>ıg</u>			29.96 in	29.96 in	Moisture	Moderate
Forward Odometer		Track Shoe Width		31.1 in	31.1 in	Packing	Moderate
Reverse Odometer						Bushing Allowable	Greater
						Wear Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% V	VORN	PROJECTED	SMU AT 100%	6 PROJECTED	SMU AT 120%		ED DATE AT 0%	PROJECTE 120	
TRACK LINK	Good	5% (1.2 in)	5% (1.2 in)								
TRACK BUSHING	Good	7% (0.44 in)	7% (0.44 in)							-	
TRACK SHOE	Good	10% (1.52 in)	10% (1.52 in)								
FRONT IDLER	Good	27% (0.79 in)	27% (0.79 in)								
CARRIER ROLLER FRONT	Good	40% (4.45 in)	40% (4.45 in)		-		-	-			
2	Good	40% (4.45 in)	40% (4.45 in)								
TRACK ROLLER	Good	0% (1.69 in)	0% (1.69 in)								
2	Good	0% (1.69 in)	0% (1.69 in)	-							
3											
	CONDITION:Guarded					CONDITION	Guarded				
4	Good	0% (1.69 in)	0% (1.69 in)								
5	Good	0% (1.69 in)	0% (1.69 in)								
6		 									
	CONDITION:Guarded					CONDITION	:				
7	Good	0% (1.69 in)	0% (1.69 in)		-					-	
8	Good	0% (1.69 in)	0% (1.69 in)								
SPROCKET	Good										
	CONDITION:Good					CONDITION	•Good				

-		