



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Christopher Thornton

Model	D6TLGP	Job Site	HM Longview		Inspection Date	19-Nov-2020
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	HTZ00400	Track Sag (1.8 in - 2.6 in)	--	--	Next Inspection Hours	--
Reference Number	HTZ400	Frame Ext (max 5.6 in)	2.9 in	2.9 in	<u>Underfoot Conditions</u>	
Hour Meter Reading	3,225.7	Dry Joints	--	--	Impact	Moderate
Hours Per Week	--	Internal Wear	0%	0%	Abrasion	Moderate
<u>Total Odometer Reading</u>	--		32 in	32 in	Moisture	Moderate
Forward Odometer	--				Packing	Moderate
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
Track Link	Left Link Assembly:4240847						Right Link Assembly:4240847								
	3788241	3788241	Original	Original	28Oct20	28Oct20	--	--	--	--	1.57 (U)	1.58 (U)	24%	22%	
Track Bushing															
	8E7222	8E7222	Original	Original	28Oct20	28Oct20	--	--	--	--	0.52 (U)	0.52 (U)	4%	4%	
Track Shoe	Left Width:36in						Right Width:36in								
	1967839	1967839	Original	Original	28Oct20	28Oct20	--	--	--	--	2.32 (U)	2.37 (U)	51%	48%	
Idlers															
Front	2024296	2024296	Original	Original	28Oct20	28Oct20	--	--	--	--	1.06 (D)	1.06 (D)	24%	24%	
Rear	2024296	2024296	Original	Original	28Oct20	28Oct20	--	--	--	--	1.04 (D)	1.04 (D)	20%	20%	
Carrier Roller															
Front	2355974	2355974	Original	Original	28Oct20	28Oct20	--	--	--	--	7.58 (C)	7.58 (C)	26%	26%	
Track Roller															
Front	S	2880934	2880934	Original	Original	28Oct20	28Oct20	--	--	--	--	1.87 (U)	1.87 (U)	1%	1%
2	D	2880935	2880935	Original	Original	28Oct20	28Oct20	--	--	--	--	1.88 (U)	1.85 (U)	0%	4%
3	S	2880934	2880934	Original	Original	28Oct20	28Oct20	--	--	--	--	--	--	--	--
CONDITION: Guarded							CONDITION: Guarded								
4	D	2880935	2880935	Original	Original	28Oct20	28Oct20	--	--	--	--	1.87 (U)	1.88 (U)	1%	0%
5	D	2880935	2880935	Original	Original	28Oct20	28Oct20	--	--	--	--	1.86 (U)	1.88 (U)	3%	0%
6	S	2880934	2880934	Original	Original	28Oct20	28Oct20	--	--	--	--	--	--	--	--
CONDITION: Guarded							CONDITION: Guarded								
												1.88	1.86		

7	D	2880935	2880935	Original	Original	28Oct20	28Oct20	--	--	--	--	(U)	(U)	0%	3%
8	S	2880934	2880934	Original	Original	28Oct20	28Oct20	--	--	--	--	1.87 (U)	1.86 (U)	1%	3%
Sprocket															
		3980972	3980972	Original	Original	28Oct20	28Oct20	--	--	--	--	8.84 (T)	8.84 (T)	1%	1%

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

General Recommendations

--