



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Christopher Thornton

Model	326FL	Job Site	HM Yard Longview		Inspection Date	19-Nov-2020
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	--
Serial Number	WGL00423	Track Sag (1.6 in - 2.1 in)	--	--	Next Inspection Hours	--
Reference Number	WGL423	Frame Ext	--	--	<u>Underfoot Conditions</u>	
Hour Meter Reading	2,030.1	Dry Joints	--	--	Impact	Moderate
Hours Per Week	--	Internal Wear	0%	0%	Abrasion	Moderate
Total Odometer Reading	--		29.95 in	29.95 in	Moisture	Moderate
Forward Odometer	--				Packing	Moderate
Reverse Odometer	--				Bushing Allowable Wear	Greater
					Link Allowable Wear	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
Track Link		Left Link Assembly:3379044						Right Link Assembly:3379044							
	3359246	3359246	Original	Original	20Aug20	20Aug20	--	--	--	--	1.2 (U)	1.2 (U)	5%	5%	
Track Bushing															
	1903523	1903523	Original	Original	20Aug20	20Aug20	--	--	--	--	0.44 (U)	0.44 (U)	7%	7%	
Track Shoe		Left Width:31.1in						Right Width:31.1in							
	5278992	5278992	Original	Original	20Aug20	20Aug20	--	--	--	--	1.51 (U)	1.52 (U)	11%	10%	
Idlers															
Front	1156337	1156337	Original	Original	20Aug20	20Aug20	--	--	--	--	0.79 (D)	0.79 (D)	27%	27%	
Carrier Roller															
Front	8E5600	8E5600	Original	Original	20Aug20	20Aug20	--	--	--	--	4.68 (C)	4.68 (C)	6%	6%	
2	8E5600	8E5600	Original	Original	20Aug20	20Aug20	--	--	--	--	4.66 (C)	4.66 (C)	9%	9%	
Track Roller															
Front	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.67 (U)	1.67 (U)	7%	7%
2	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.68 (U)	1.67 (U)	4%	7%
3	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
4	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.69 (U)	1.68 (U)	0%	4%
5	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.69 (U)	1.69 (U)	0%	0%
6	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
7	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.68 (U)	1.68 (U)	4%	4%

8	S	3481867	3481867	Original	Original	20Aug20	20Aug20	--	--	--	--	1.68 (U)	1.68 (U)	4%	4%
Sprocket															
		1028134	1028134	Original	Original	20Aug20	20Aug20	--	--	--	--	--	--	--	--
CONDITION: Good									CONDITION: Good						

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

General Recommendations

--