



## Custom Track Service Percent Worn

**HOLT TEXAS LTD.**

**HOWARDMCANEAR EQUIPMENT**  
(0585540)

Prepared By: Cory Whitaker

<b>Model</b>	D8T	<b>Job Site</b>	HM FW		<b>Inspection Date</b>	13-Oct-2020
<b>Manufacturer</b>	Caterpillar		<u>Left</u>	<u>Right</u>	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	FMC00282	<b>Track Sag (4.1 in - 4.9 in)</b>	--	--	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	282	<b>Frame Ext (max 6.0 in)</b>	2.45 in	2.5 in	<b><u>Underfoot Conditions</u></b>	
<b>Hour Meter Reading</b>	1,566.6	<b>Dry Joints</b>	--	--	<b>Impact</b>	Moderate
<b>Hours Per Week</b>	--	<b>Internal Wear</b>	0%	0%	<b>Abrasion</b>	Moderate
<b><u>Total Odometer Reading</u></b>	--				<b>Moisture</b>	Moderate
<b>Forward Odometer</b>	--				<b>Packing</b>	Moderate
<b>Reverse Odometer</b>	--			34.05 in 34.05 in	<b>Bushing Allowable Wear</b>	Greater
					<b>Link Allowable Wear</b>	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
<b>Track Link</b>		<b>Left Link Assembly:2726009</b>				<b>Right Link Assembly:2726009</b>									
	8E4513	8E4513	Original	Original	--	--	--	--	--	--	1.84 (U)	1.84 (U)	8%	8%	
<b>Track Bushing</b>															
	6Y3914	6Y3914	Original	Original	--	--	--	--	--	--	0.59 (U)	0.59 (U)	4%	4%	
<b>Track Shoe</b>		<b>Left Width:24in</b>				<b>Right Width:24in</b>									
	7T2392	7T2392	Original	Original	--	--	--	--	--	--	3.8 (U)	3.8 (U)	13%	13%	
<b>Idlers</b>															
<b>Front</b>	1111729	1111729	Original	Original	--	--	--	--	--	--	0.82 (D)	0.82 (D)	8%	8%	
<b>Rear</b>	1111729	1111729	Original	Original	--	--	--	--	--	--	0.82 (D)	0.82 (D)	8%	8%	
<b>Track Roller</b>															
<b>Front</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	2.42 (U)	2.44 (U)	6%	4%	
<b>2</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	2.44 (U)	2.44 (U)	4%	4%	
<b>3</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	2.34 (U)	2.35 (U)	4%	2%	
<b>4</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	2.34 (U)	2.34 (U)	4%	4%	
<b>5</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	2.35 (U)	2.35 (U)	2%	2%	
<b>6</b>	D	2460779	2460779	Original	Original	--	--	--	--	--	2.34 (U)	2.34 (U)	4%	4%	
<b>7</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	2.44 (U)	2.43 (U)	4%	5%	
<b>8</b>	S	2460775	2460775	Original	Original	--	--	--	--	--	2.45 (U)	2.44 (U)	3%	4%	
<b>Sprocket</b>															

	3145462	3145462	Original	Original	--	--	--	--	--	--	9.32 (T)	9.3 (T)	11%	14%
--	---------	---------	----------	----------	----	----	----	----	----	----	-------------	---------	-----	-----

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape

## General Recommendations

UC ALL GOOD

Photos

Pre-Inspect

---



Pre-Inspect



Pre-Inspect

---