



## Custom Track Service Percent Worn

**HOLT TEXAS LTD.**

**HOWARDMCANEAR EQUIPMENT**  
(0585540)

Prepared By: Christopher Thornton

<b>Model</b>	D6K2LGP	<b>Job Site</b>	HM Yard Longview		<b>Inspection Date</b>	19-Nov-2020
<b>Manufacturer</b>	Caterpillar		<u>Left</u>	<u>Right</u>	<b>Next Inspection Date</b>	--
<b>Serial Number</b>	RST01914	<b>Track Sag (1.5 in - 2 in)</b>	--	--	<b>Next Inspection Hours</b>	--
<b>Reference Number</b>	RST1914	<b>Frame Ext</b>	--	--	<b><u>Underfoot Conditions</u></b>	
<b>Hour Meter Reading</b>	1,908	<b>Dry Joints</b>	--	--	<b>Impact</b>	--
<b>Hours Per Week</b>	--	<b>Internal Wear</b>	0%	0%	<b>Abrasion</b>	--
<b><u>Total Odometer Reading</u></b>	--		29.95 in	29.95 in	<b>Moisture</b>	--
<b>Forward Odometer</b>	--				<b>Packing</b>	--
<b>Reverse Odometer</b>	--				<b>Bushing Allowable Wear</b>	Greater
					<b>Link Allowable Wear</b>	Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (inches)		Percent Worn		
	Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right
<b>Track Link</b>		<b>Left Link Assembly:1102976</b>						<b>Right Link Assembly:1102976</b>							
	1061625	1061625	Original	Original	18Nov20	18Nov20	--	--	--	--	1.5 (U)	1.5 (U)	9%	9%	
<b>Track Bushing</b>															
	1061618	1061618	Original	Original	18Nov20	18Nov20	--	--	--	--	0.49 (U)	0.49 (U)	8%	8%	
<b>Track Shoe</b>		<b>Left Width:29.9in</b>						<b>Right Width:29.9in</b>							
	3798893	3798893	Original	Original	18Nov20	18Nov20	--	--	--	--	2.55 (U)	2.54 (U)	16%	17%	
<b>Idlers</b>															
<b>Front</b>	3689791	3689791	Original	Original	18Nov20	18Nov20	--	--	--	--	1.01 (D)	1 (D)	14%	12%	
<b>Carrier Roller</b>															
<b>Front</b>	3723375	3723375	Original	Original	18Nov20	18Nov20	--	--	--	--	6.46 (C)	6.47 (C)	15%	14%	
<b>2</b>	3723375	3723375	Original	Original	18Nov20	18Nov20	--	--	--	--	6.5 (C)	6.48 (C)	12%	13%	
<b>Track Roller</b>															
<b>Front</b>	S	3650752	3650752	Original	Original	18Nov20	18Nov20	--	--	--	--	1.39 (U)	1.38 (U)	22%	24%
<b>2</b>	D	3650751	3650751	Original	Original	18Nov20	18Nov20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
<b>3</b>	S	3650752	3650752	Original	Original	18Nov20	18Nov20	--	--	--	--	1.44 (U)	1.42 (U)	12%	16%
<b>4</b>	D	3650751	3650751	Original	Original	18Nov20	18Nov20	--	--	--	--	1.42 (U)	1.41 (U)	16%	18%
<b>5</b>	D	3650751	3650751	Original	Original	18Nov20	18Nov20	--	--	--	--	1.41 (U)	1.41 (U)	18%	18%
<b>6</b>	S	3650752	3650752	Original	Original	18Nov20	18Nov20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
<b>7</b>	D	3650751	3650751	Original	Original	18Nov20	18Nov20	--	--	--	--	1.4 (U)	1.41 (U)	20%	18%

8	S	3650752	3650752	Original	Original	18Nov20	18Nov20	--	--	--	--	--	--	--	--
CONDITION: Guarded								CONDITION: Guarded							
<b>Sprocket</b>															
		3613977	3613977	Original	Original	18Nov20	18Nov20	--	--	--	--	--	--	--	--
CONDITION: Worn								CONDITION: Worn							

(U) Ultrasonic | (C) Caliper | (D) Depth Gauge | (T) Tape

## General Recommendations

--