



Custom Track Service Percent Worn

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT
(0585540)

Prepared By: Matthew Davis

Model	D6-20VP	Job Site	--	Inspection Date	20-Apr-2021
Manufacturer	Caterpillar	Left		Right	
Serial Number	RBP00322	Track Sag (46 mm - 66 mm)	--		
Reference Number	--	Frame Ext (max 142 mm)	75 mm	73 mm	Next Inspection Date --
Hour Meter Reading	1,624	Dry Joints	--		Next Inspection Hours --
Hours Per Week	--				Underfoot Conditions
Total Odometer Reading	--				Impact --
Forward Odometer	--				Abrasion --
Reverse Odometer	--				Moisture --
					Packing --
					Bushing Allowable Wear Greater
					Link Allowable Wear Greater

Position	Part Number		Status		Date Installed		SMU Installed		Hours on Wear Surface		Measurement (mm)		Percent Worn		
Component	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	Left	Right	
Link Assemblies										Left:5429401			Right:5429401		
Track Link	2482307	2482307	Original	Original	19Apr21	19Apr21	1624	1624	0	0	127 (D)	128 (D)	38%	30%	
Bushing (Ext)	8E7222	8E7222	Original	Original	19Apr21	19Apr21	1624	1624	0	0	12.6 (U)	12.7 (U)	12%	12%	
Track Shoe										Left Width:610mm			Right Width:610mm		
	6Y6287	6Y6287	Original	Original	19Apr21	19Apr21	1624	1624	0	0	60 (D)	61 (D)	19%	15%	
Idlers															
Front	2061897	2061897	Original	Original	19Apr21	19Apr21	1624	1624	0	0	25 (D)	25 (D)	8%	8%	
Rear	2061897	2061897	Original	Original	19Apr21	19Apr21	1624	1624	0	0	25 (D)	25 (D)	8%	8%	
Carrier Roller															
Front	2355974	2355974	Original	Original	19Apr21	19Apr21	1624	1624	0	0	198 (C)	199 (C)	4%	1%	
Track Roller															
Front	S	2880934	2880934	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.7 (U)	45.9 (U)	12%	10%
2	D	2880935	2880935	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.8 (U)	45.7 (U)	12%	12%
3	S	2880934	2880934	Original	Original	19Apr21	19Apr21	1624	1624	0	0	--	--	--	--
CONDITION: Guarded									CONDITION: --						
4	D	2880935	2880935	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.7 (U)	45.5 (U)	12%	13%
5	D	2880935	2880935	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.2 (U)	45.4 (U)	15%	13%
6	S	2880934	2880934	Original	Original	19Apr21	19Apr21	1624	1624	0	0	--	--	--	--
CONDITION: Guarded									CONDITION: --						
7	D	2880935	2880935	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.6 (U)	45.6 (U)	12%	12%
8	S	2880934	2880934	Original	Original	19Apr21	19Apr21	1624	1624	0	0	45.8 (U)	45.5 (U)	12%	13%
Sprocket															

	--	--	Original	Original	19Apr21	19Apr21	1624	1624	0	0	225 (T)	225 (T)	--	--
CONDITION: Good							CONDITION: Good							

(U) Ultrasonic I (C) Caliper I (D) Depth Gauge I (T) Tape

General Recommendations

--