

Custom Track Service **Projected Life**

HOLT TEXAS LTD.

HOWARDMCANEAR EQUIPMENT (0585540)

Prepared By: Daryl Brumfield

Model	D6TXL	Job Site			Inspection Date	07Dec21
Manufacturer	Caterpillar		<u>Left</u>	<u>Right</u>	Next Inspection Date	
Serial Number	NDY00489	Track Sag (1.8 in - 2.6 in)	1.2 in	1.6 in	Next Inspection Hours	
Reference Number		Frame Ext (max 5.8 in)	2.5 in	2.5 in	Underfoot Conditions	
Hour Meter Reading	1,713	Frame Ext %	43%	43%	Impact	Moderate
Hours Per Week		Dry Joints	0	0	Abrasion	Moderate
Total Odometer Reading		Track Shoe Width	24.1 in	24.1 in	Moisture	Moderate
Forward Odometer		Link Roller System	21%	19%	Packing	Moderate
Reverse Odometer					Bushing Allowable	Greater
Distance Per Week					Wear Link Allowable Wear	Greater

GROUP	RECOMMENDATION	% V	VORN	PROJECTED	SMU AT 100%	PROJECTED	SMU AT 120%		ED DATE AT 0%	PROJECTE 120	
TRACK LINK	Good	20% (1.59 in)	16% (1.61 in)								
BUSHING (INT)	Good	0% (32 in)	0% (32 in)								
BUSHING (EXT)	Monitor	52% (0.39 in)	48% (0.41 in)								
TRACK SHOE	Good	10% (3.39 in)	7% (3.43 in)								
FRONT IDLER	Good	28% (1.08 in)	26% (1.07 in)								
REAR IDLER	Good	22% (1.05 in)	20% (1.04 in)								
CARRIER ROLLER FRONT	Good	16% (7.68 in)	16% (7.68 in)								
TRACK ROLLER FRONT	Good	12% (1.8 in)	12% (1.8 in)								
2											
	CONDITION:Guarded CONDITION:Guarded										
3	Good	15% (1.79 in)	13% (1.8 in)								
4	Good	13% (1.8 in)	15% (1.79 in)								
5											-
	CONDITION:Guarded					CONDITION:Guarded					
6	Good	10% (1.82 in)	12% (1.81 in)								
7	Good	22% (1.73 in)	21% (1.74 in)								
SPROCKET	Monitor	60% (8.4 in)	60% (8.4 in)								

Photos Pre-Inspect





Pre-Inspect

Pre-Inspect